

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
1	BRS	344	(172/\$.cc1s. 37/\$.cc1s.) and ((ball with joint) (ball with socket) (ball-and-socket)) and frame and mounting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/11 11:27		
2	BRS	262	(172/\$.cc1s. 37/\$.cc1s.) and ((ball with joint) (ball with socket) (ball-and-socket)) and frame and mounting and (actuator cylinder)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/11 11:49		
3	BRS	73	(172/810-834.cc1s. 37/234-236.cc1s.) and ((ball with joint) (ball with socket) (ball-and-socket)) and frame and mounting and (actuator cylinder)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/11 12:27		
4	BRS	5	4562891.URPN.	USPAT	2004/05/11 12:04		
5	BRS	3	("3529678" "3822751" "4405019") .PN.	USPAT	2004/05/11 12:06		
6	BRS	33	(172/810-834.cc1s. 37/234-236.cc1s.) and ((ball with joint) (ball with socket) (ball-and-socket)) and brace and (actuator cylinder)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/11 14:12		